



# BUILDING ENERGY 15

MARCH 3-5, 2015 AT THE SEAPORT WORLD TRADE CENTER

AIA Provider: Northeast Sustainable Energy Association

Provider Number: G338


## Super Insulated Walls and Moisture:

## Does Bad Stuff Happen?

Course Number

## Chris Corson and Kohta Ueno

March 4, 2015



Credit(s) earned on completion of this course will be reported to **AIA CES** for AIA members. Certificates of Completion for both AIA members and non-AIA members are available upon request.

**CES** for continuing professional education. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product.

---

Questions related to specific materials, methods, and services will be addressed at the conclusion of this presentation.

This course is registered with **AIA**



# Course Description

---

High-R or super-insulated walls are a common component of high performance housing. However, in cold climates, these walls run the risks of cold-weather condensation, and general durability issues due to reduced heat flow. Two practitioners have been monitoring the moisture performance of several high performance walls, and will share their results. Chris Corson has been examining highly vapor-open walls based on classic European Passive House designs, without the use of plastic foams. Kohta Ueno has been monitoring double stud walls insulated with cellulose and open-cell spray foam for three winters. His monitoring study was followed by disassembly of the walls, to examine conditions in the cavities. The two will talk about their data, whether various assemblies fall on the safer or riskier side, and how to make design choices. Keeping these walls buildable and cost-effective will be another aspect of the discussions.

# Learning Objectives

---

At the end of the this course, participants will be able to answer:

1. What are the risks associated with high-R or superinsulated walls, relative to conventional/code construction?
2. What are some of the options for constructing high-R walls in cold climates?
3. How does a vapor-open high-R wall behave in a very cold climate (Maine), in terms of moisture risks?
4. What moisture conditions and resulting damage are seen at double stud wall sheathing after experiencing high interior humidity conditions?

Kohta Ueno

# Super Insulated Walls and Moisture: Does Bad Stuff Happen? (Double Stud)

---

NESEA BuildingEnergy 2014

March 4, 2015



© buildingscience.com



**BUILDING ENERGY 15**

MARCH 3-5, 2015 AT THE SEAPORT WORLD TRADE CENTER

---

# Background

# Double Stud Wall Monitoring




---

- Double stud wall advantages:
  - High R values
  - Simplifies exterior detailing (few changes to standard practice)
  - Lower cost vs. other high-R walls?
- Moisture risks due to interstitial condensation?
  - Most common failure, after rain control issues
  - Air barrier imperfections—increase risk
  - Air permeable low-density insulations—increase risk (including convective looping)
  - Air impermeable insulations—decrease risk
  - Reduce risk with “skim” of spray foam at sheathing?



# Wall Condensation Potentials




Double stud wall



Structural sheathing

Foundation wall

4" insulating sheathing (on 2x6)



4" polyisocyanurate insulation

Structural sheathing

Foundation wall

---


# Experimental Setup

# Wall Construction


- Vinyl siding
- ZIP wall sheathing (OSB)
- Class III vapor control (latex paint)
- IRC R601.3.1—vented cladding over OSB



# Site and Orientation



# Test Wall Locations (2<sup>nd</sup> Floor)




**Wall 1 = 12" o.c. SPF**

**Wall 2 = 12" Cellulose**


**Wall 3 = 5-1/2" o.c. SPF**

# Test Wall Instrumentation


Upper Wall Sensors



Mid-Height Sensors



Lower Wall Sensors




## Sensor Key:

- ▲ Temperature
- Relative humidity/temperature
- Moisture content/temperature
- Moisture content block




# Test Wall Instrumentation


Upper Wall Sensors



Mid-Height Sensors



Lower Wall Sensors



## Sensor Key:

- ▲ Temperature
- Relative humidity/temperature
- Moisture content/temperature
- Moisture content block


---

# Results: Boundary Conditions




# Data Collected

- December 2011 through July 2014 (32 months)
- Three winters collected (one partial)
- Warmer, normal, & colder winters



# Boundary Conditions



# Boundary Conditions Takeaways



---

- First Winter (Partial)
  - Unoccupied conditions (no occupant moisture generation)
  - **Very low interior RH**
  - 5220 HDD Base 65 vs. 6220 HDD “normal”
- Second Winter
  - Occupied family of four (2 adults, 2 children)
  - Ventilation system not running, ~1 ACH 50 → **High RHs**
- Third Winter
  - Winter of the “polar vortex”
  - Occupied conditions (same family)
  - Ventilation system running → **RHs ~15-30%**



---

# Results: Wall Monitoring


# Sheathing Moisture Content (North)



# Sheathing Moisture Content (South)





# Sheathing "Wafer" Moisture Contents



- 100% RH
- → liquid water immersion
- in condensation at sheathing
- condensation on south side



# Relative Humidity Comparison






---



# Sheathing Temperature

# Colder Sheathing with More Insulation?



- Outdoor temperature 50 F (10:30 AM)

# Colder Sheathing with More Insulation?



# Colder Sheathing with More Insulation?


---

- Double stud wall sheathing maybe ~1 F or less colder at coldest conditions
- Steady state analysis predicts 0.8 F difference @ 7 F outdoors
- Wintertime energy/Btu's through sheathing possibly more important (drying energy): doubling insulation = halving heat flow
- 12" vs. 5.5" cavity insulation different than cavity vs. exterior insulation!

---

# Wall Disassembly

# South Side Disassembly



# South Side Disassembly



# North Side Disassembly






# North Side Disassembly



# North Side Disassembly

---



---

# Analysis

# Vapor Permeability of Insulation Layer

Wall ID	Insulation Material	Vapor Permeability (Insulation Only)	Vapor Permeability (Add 10 Perm Class III Vapor Retarder)
N1/S1	12 in. 0.5 PCF foam	1.8–2.5 perms	1.5–2.0 perms
N2/S2	12 in. cellulose	7.0–10 perms	4.0–5.0 perms
N3/S3	5-½ in. 0.5 PCF foam	4.0–5.5 perms	2.9–3.5 perms

- Insulation-only, vs. adding 10 perm Class III vapor retarder (latex paint)
- 12” of ocSPF (brand used here) provides reasonable interior vapor control


# Why Aren't The Walls Oatmeal?

---

- 20% MC or lower—decay fungi inhibited
- Best growth 25-30% MC range
- All walls had MCs over 20% in winter 2; cellulose 30%+
- Condensation indicated—liquid water is kicker for decay activity

# ASHRAE 160—Wet and Warm Enough?

- 30 day running average
  - Relative humidity > 80% AND
  - Temperature between 41 F and 104 F
- T & RH @ insulation-sheathing interface




# Protective Mechanisms


---

- OSB Sheathing—all MDI adhesive
- Cellulose fiber insulation
  - Borate preservative/fire retardant—also leaches into adjacent materials
  - Moisture storage in cellulose
  - Airflow retarding qualities
- Open cell polyurethane spray foam
  - Oxygen restriction?

# ocSPF Protective Mechanisms



Open-cell SPF



Closed-cell SPF

Images c/o SPFA

- Food science literature—oxygen needs to be in PPM range before inhibiting mold growth. Mold can get oxygen from substrate.



# Protective Mechanisms

---

- OSB Sheathing—all MDI adhesive (no PF)
- Cellulose fiber insulation
  - Borate preservative/fire retardant—also leaches into adjacent materials
  - Moisture storage in cellulose
  - Airflow retarding qualities
- Open cell polyurethane spray foam
  - Oxygen restriction?
  - “Flash heating”? Hot enough long enough?
  - Surface treatment (film formation)?
  - Capillary redistribution (through ocSPF pores)?

---

# Conclusions

# Monitoring Conclusions

---

- “Normal” interior RH conditions:
  - ocSPF walls stayed below 20% MC—**SAFE**
  - Cellulose > 20% MC on north—**WORRYING**, BUT...
- High interior RH conditions
  - ocSPF walls peaked in 18-25% MC range
  - Cellulose >30% MC, condensation indicated
- Each summer, walls dried to safe conditions
- ASHRAE 160 and mold isopleths say these walls have failed
- Disassembly showed all walls look okay
  - Sheathing reinstalled

# Construction Recommendations

---

- Based on Zone 5A Climate
- Cellulose walls
  - Class III (latex paint) risky
  - Class II (VR paint, variable-permeability membrane safer)
  - Class I (polyethylene) NOT recommended
- ocSPF walls
  - ocSPF seems to provide sufficient vapor control
  - Class II possible option on conservative side
- Mechanical ventilation system vital
- Exterior insulated walls much more moisture-safe!

This concludes The American Institute of Architects  
Continuing Education Systems Course

---



---

# Questions?

Kohta Ueno (kohta [at sign] buildingscience [dot] com)

This presentation will be available at:

<http://www.buildingscienceconsulting.com/presentations/recent.aspx?PresentationsYear=2015>

The full Building America report on this research:

<http://www.buildingscience.com/documents/bareports/ba-1501-monitor-double-stud-moisture-conditions-northeast/view>

U.S. DEPARTMENT OF  
**ENERGY** | Energy Efficiency &  
Renewable Energy

